



Information Circular No: **2010/5** Date: 22 February 2010

TO: SENATORS, MEMBERS AND OTHER BUILDING OCCUPANTS

Replacement of external fire hydrants

1 The existing 17 high capacity fire hydrants on the outer perimeter of Parliament Drive require replacement due to corrosion and metal fatigue in the tap mechanisms. Work will proceed on two hydrants at any time. The work should be completed by mid April. A layout of the hydrants is attached.


2 This work will necessitate the temporary closing of one lane of Parliament Drive in close proximity to each hydrant. To avoid traffic congestion, lane closures will not be implemented in the areas close to the entrances to car parks until after 9:30 AM daily. In addition there will be no work on this project during the impending international Heads of State visits.


3 For further information about the hydrants, please contact Mr David Rayner, DPS Project Manager on (02) 6277 5157.

4 Before I conclude, I would like to note that the Parliament Drive resurfacing works are now largely complete, with only minor works such as line marking and signs to be completed. I thank all building occupants for your cooperation, particularly over the week of 15 to 19 February.

Alan Thompson
Secretary

High Capacity Hydrant Locations



 High Capacity Hydrant