



Information Circular No: **2010/18** Date: 31 May 2010

---


TO: SENATORS, MEMBERS AND OTHER BUILDING OCCUPANTS

**Glazing replacement to Senate link way**

- 1 The Department of Parliamentary Services will be replacing two broken panes of glass in the link way located to the south of the Senate Chamber as shown on the attached plan. This work will occur between 3 and 9 June 2010.
- 2 Scaffolding will be erected in the outer courtyard (area 28K—see attached plan) between 3-4 June. Glass replacement is expected to happen on 8 June 2010.
- 3 There will be no access via the second level link way on 8 June; however link way access will be available via level 1 and the ground floor.
- 4 Access to the outer courtyard will be maintained throughout, but there will be restrictions around the construction zone.
- 5 Please contact David Dobson on extn 5566 if you require further information.

Alan Thompson  
Secretary

Information Circular No 18  
 Glazing replacement to Senate link way



Title **GLAZING REPLACEMENT TO SENATE LINKWAY**