

Senate Finance and Public Administration Legislation Committee

ANSWERS TO QUESTIONS ON NOTICE

Prime Minister and Cabinet Portfolio

Department of the Prime Minister and Cabinet

Supplementary Budget Estimates 19 October 2009

Question: PM19(a-b)

Topic: Kirribilli House

Type of Question: Written

Date set by the committee for the return of answer: 4 December 2009

Number of pages: 2

- a) **Can you provide a list, including costs, of all renovations and repairs undertaken at Kirribilli House and The Lodge since 1 January 2009?**
- b) **Can you provide a list, including costs, of all new capital equipment supplied to Kirribilli House and The Lodge since 1 January 2009?**

Answer:

- a) The following property repairs or renovations were undertaken and paid for at Kirribilli House between 1 January and 10 November 2009:

Work undertaken	Cost (GST exclusive)
Call out for repair of zip boil in kitchen	\$ 150.00
Replace faulty circuit breaker in guard box	230.93
Repair and parts for zip boil in kitchen	129.30
Repair window pane on upstairs landing	215.00
Repair taps in laundry and gardeners shed	735.00
Repair toilet cistern in gardeners shed	265.50
Replacement of kitchen exhaust fan and related ducting	3,200.00
Internal and external remedial paintworks	17,196.80
Total	\$ 22,122.53

Senate Finance and Public Administration Legislation Committee

ANSWERS TO QUESTIONS ON NOTICE

Prime Minister and Cabinet Portfolio

Department of the Prime Minister and Cabinet

Supplementary Budget Estimates 19 October 2009

The following property repairs or renovations were undertaken and paid for at The Lodge between 1 January and 10 November 2009:

Work undertaken	Cost (GST exclusive)
Install magnetite window treatment to master suite	\$ 2,351.82
Remove dead possum from water pipes	190.00
Surface repair to bathroom wall	61.22
Repair to various light fittings	200.00
Repair of faulty air conditioning unit (compressor and other parts)	3,025.00
Inspect water leak to air conditioning unit	140.00
Repair of fridge and cool room	976.00
Internal and external remedial paintworks	15,055.00
Replace rotten flagpole, replace rotten balcony handrails and repair timber columns	3,450.00
Clear blocked drains	1,381.50
Total	\$ 26,830.54

- b) There have been no new capital equipment purchases at either residence since 1 January 2009.