EDUCATION, SCIENCE AND TRAINING

SENATE LEGISLATION COMMITTEE - QUESTIONS ON NOTICE 2007-2008 BUDGET ESTIMATES HEARING

Outcome CSIRO

DEST Question No. E021_08

Senator Carol Brown asked in writing on 30 May 2007.

Question:

Specifically can you provide the committee with the details of any work that was conducted by the contracted company *Taylor Brothers* during this period, including the date and nature and reason for the work?

Answer:

CSIRO has provided the following response.

Southern Surveyor

During May 2007 Taylor Brothers, who are selected by P&O, conducted the work below.

Date	Reason for Work	Nature of Work
3/05/2007	Guard rails corroded	Repair
3/05/2007	Impellar wear rings & mount ring worn (2)	Replace
4/05/2007	Sounding pipe corroded	Repair
4/05/2007	Steering gear hydraulic mounting block failure	Repair and inspect
4/05/2007	Lab Deck Heads corroded	Replace
4/05/2007	Towed body winch creeping	Repair
4/05/2007	Holding down bolts coring winch	Inspect
4/05/2007	AC Fan bearings worn	Replace
4/05/2007	Aft Deck Camera obstructed	Relocate
8/05/2007	Fire Main Isolating Valves	Overhaul
8/05/2007	Main Mast Access poor	Fit ladder
8/05/2007	Damaged deck fittings	Repair
8/05/2007	ER Watertight closing device requirement upgraded	Fabricate & Fit
8/05/2007	Fire doors	Repair heavy weather damage
8/05/2007	Air intake noisy	Fit acoustic baffling
9/05/2007	Windlass Hydraulic motor worn	Replace
9/05/2007	Hospital & Bosuns Toilet Deck corroded	Repair
10/05/2007	Stripped thread in CPP	Repair
10/05/2007	Emerbond paint	Supply
14/05/2007	Fresh & Sanitary water piping	Flush & prove clear
14/05/2007	20 x M24 eye bolts for securing equipment to deck	Supply
15/05/2007	Ventilation Pipework corroded	Repair
15/05/2007	SW line to evap corroded	Repair
15/05/2007	S/W piping to A/C Unit corroded	Replace
15/05/2007	Air Conditioning replacement	Trades assistance
15/05/2007	Water leak on # 2 Alternator	Repair
15/05/2007	Leak under LO Cooler	Repair
16/05/2007	Corrosion resistant sewage holding tanks	Install
16/05/2007	Butterfly check valve corroded	Supply & fit
17/05/2007	FW suction & line to MCR chiller	Repair
17/05/2007	Stainless Steel bar	Supply
18/05/2007	Gas-free certificate	Supply
21/05/2007	HW temp gauges & pressure	Supply and fit